

U. S. Department of Agriculture
FOREST SERVICE

Posted

R 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

Section Corner common to Sections

20, 21, 29, and 30


Corner consists of a Br. cap. 2" iron pipe (not) in place
State condition good

Dimensions above ground 5" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144 N. R 30 W S 21	S 20	S 29	S 28
B. T.	B. T.	B. T.	B. T.

Species	W. Spruce	W. Pine	W. Birch	W. Pine
Diameter	15"	20"	4"	80"
Bearing	N 8° 15' E	N 55° 45' W	S 16° 45' W	S 82° 15' E
Distance	70	102	27 3/4	28

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? _____

Dorman J. Sutton

(Signature)

Sept 10, 1934

(Date)

Compass man

(Title)

Dotted lines for writing notes.

Corner again.

Give any further facts which will aid in finding this

chains distant.


28

from which this Corner bears N 82° 15' W

side of tree

tree 30 inches diameter, on the N.W.

Metal Location Poster is on a W.P.M.



(Make sketch of topography near Corner)

Mer.

674

R. 30W

T. 144N