

E-11
Posted

E11

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5th Mer.

Quarter Corner common to Sections
.....,, 9, and 9.....



Corner consists of a Brass capped pipe (not) in place
State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4} S 9$	$\frac{1}{4} S 9$		
B.T.	B.T.		

Species Elm Ash

Diameter 6" 14"

Bearing N 9° 15' W S 11° 45' W

Distance 5 $\frac{3}{4}$ 92 $\frac{1}{2}$

Do you believe this to be a genuine Land Office Corner? Yes


If not, why?

Forrest Sandberg
(Signature)

10-25-34
(Date)

Const. Foreman
(Title)

Metal Location Poster is on an *FLM*
 tree *6*" inches diameter, on the *S. E.*
 side of *Bearing tree*
 from which this Corner bears *N. 90° 15' W.*
0.92 1/2 chains distant.
 Give any further facts which will aid in finding this
 Corner again.



(Make sketch of topography near Corner)

T. 194N R. 30 W. S+4 Mer.