

U. S. Department of Agriculture
FOREST SERVICE

P-13
p. 13
Potted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer.

Quarter

Corner common to Sections

21, and 22

Corner consists of a Broom¹ iron (not) in place


State condition good

Dimensions above ground 12" Inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4
S22

1/4
S21

B.T.

B.T.

Species B. Spruce B. Spruce

Diameter 4" 4 1/2"

Bearing S74°30'E S39°30'W

Distance 4 1/2 lk. 79 lk.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton

(Signature)

Compassman

(Title)

10-1-34
(Date)

P-13

Corner again.

Give any further facts which will aid in finding this


chains distant.

H15

from which this Corner bears N 88° 30' W

side of tree

Metal Location Poster is on a B. Spruce tree 4 1/2" inches diameter, on the NW



(Make sketch of topography near Corner)

T. 144 N. R. 30 W. 579 P-13