

U. S. Department of Agriculture  
FOREST SERVICE

C-13

*Patented*  
C13

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N.* R. *30 W.* *5<sup>th</sup>* Mer.

*Quarter* Corner common to Sections

*3*, and *4*

Corner consists of a *Brass capped Pipe (not)* in place

State condition *Good*

Dimensions above ground *9* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>1/4</i> <i>S 3</i>	<i>1/4</i> <i>S 4</i>		
<i>B.T.</i>	<i>B.T.</i>		

Species *BIRCH* *BIRCH*

Diameter *14"* *8"*

Bearing *N 54° 25' E* *S 61° 45' W*

Distance *89* *68 1/4*

Do you believe this to be a genuine Land Office Corner? *YES*

If not, why? \_\_\_\_\_

*Bryan Leit*  
(Signature)

*Compassman*  
(Title)

*10-31-34*  
(Date)

C-13

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


----- 068 1/4 chains distant.

----- from which this Corner bears N 61° 45' E

----- side of TREE

----- tree 8" inches diameter, on the NE

----- Metal Location Poster is on a BIRCH



(Make sketch of topography near Corner)