

U. S. Department of Agriculture  
FOREST SERVICE

Posted  
V-15

Shippawa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 194 N. R. 30 W. 5<sup>th</sup> Mer.


Quarter Corner common to Sections  
27, and 34

Corner consists of a Brass capped pipe (not) in place  
State condition Good

Dimensions above ground 6 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

B.T.

Species Cedar Cedar

Diameter 8" 12"

Bearing N. 7° 10' E S. 61° 45' W.

Distance 1.7 16 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

F. F. Sandberg

(Signature)

10-11-34

(Date)

Const. Foreman

(Title)

Lined writing area with horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


..... chains distant.

from which this Corner bears N. 17° 15' W.

side of tree

tree 12 inches diameter, on the S.E.

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 19 N. R. 30 W.

5+4 Mer.

V-15