

T-15

U. S. Department of Agriculture

FOREST SERVICE

posted
15

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 140 N R. 30 W S. 5 Mer.

C 1/2 Corner common to Sections

27, and

Corner consists of a metal hub (not) in place


State condition good

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

 Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species ash

Diameter 11"

Bearing

Distance 6'

Do you believe this to be a genuine Land Office Corner?.....

If not, why?

[Signature]
(Signature)

Nov 18-21
(Date)

[Signature]
(Title)

T-15

<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>
<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>	<p>Sec.</p>

(Make sketch of topography near Corner)

Metal Location Poster is on a tree _____ inches diameter, on the side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

Metal Location Poster

T. L. M. A. R. 30 W. Mer. 7-15