

U. S. Department of Agriculture  
FOREST SERVICE

*Posted*

Chippewa NATIONAL FOREST

E-15

CORNERS OF THE PUBLIC SURVEY

T. 144N. R. 30W. 5<sup>th</sup> Mer. Quarter

Corner common to Sections 3, and 10


Corner consists of a Br. cap. iron pipe in place  
State condition good

Dimensions above ground 9" x 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$   
S3

$\frac{1}{4}$   
S10

B.T.

B.T.

Species Elm Elm

Diameter 9 10"

Bearing N 88° 15' E S 92° 30' E

Distance 44 1/2 73 1/2 *lks.*

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Dorman J. Sutton*

(Signature)

10-25-34

(Date)

Compassman

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *588°15' W*

side of *tree*

tree *9* inches diameter, on the *SW*

Metal Location Poster is on a *Flm*



(Make sketch of topography near Corner)

*E-75*  
Met.

*62*

*R. 30W*

*T. 144N*