

R-16

U. S. Department of Agriculture  
FOREST SERVICE

R-16 Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5<sup>th</sup> Mer.


Sixteenth Corner common to Sections  
22, and 27

Corner consists of a Brass capped pipe (not) in place  
State condition Good

Dimensions above ground 8 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E 1/16
S 22

E 1/16
S 27



B. T.

B. T.

Species W. Oak W. Oak

Diameter 10" 18"

Bearing N 10° 40' E S 51° 20' W

LKs Distance 35 36

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

F. E. Sandberg

(Signature)

10-15-34

(Date)

Const. Foreman

(Title)

R-16

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T 144N R. 30 W. S 74 B-16 Mer.