

T-17

U. S. Department of Agriculture

FOREST SERVICE

*posted*

*Chippewa*

NATIONAL FOREST

T-17

CORNERS OF THE PUBLIC SURVEY

T. *144* R. *304* S. *5* Mer.

Corner common to Sections

*27*, and *26*

Corner consists of a *2 1/2" Brass Cal.* (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>144</i>	<i>27</i>		<i>26</i>
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>144</i> <i>539</i>	<i>144</i> <i>526</i>		
<i>37</i>	<i>37</i>		

Species *Ced. 1* *Ced. 1*

Diameter *10"* *6"*

Bearing *N 76°* *N 7 E*

Distance *51* *51*

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

(Signature)

*E. Liberator*

*Nov. 1931*

(Date)


(Title)

T-17

7-7

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)