

U. S. Department of Agriculture  
FOREST SERVICE

Post # 17

Shippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer.

Section Corner common to Sections

22, 23, 24, and 27.

Corner consists of a Brass capped pipe (not) in place

State condition Good

Dimensions above ground 14 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 144N  
R. 30W  
S 22

T. 144N  
R. 30W  
S 23

T. 144N  
R. 30W  
S 24

T. 144N  
R. 30W  
S 27

B. T.

B. T.

B. T.

B. T.

Species Tam. Tam. W. Pine Cedar

Diameter 10" 8" 18" 14"

Bearing N. 26° 30' W N. 8° E S 12° 45' E S 30° 30' W

Distance 203 89 34 71

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

F. F. Sandberg

(Signature)

10-11-34

(Date)

Const. Foreman

(Title)

Handwritten notes on a series of horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


0.21 chains distant.

from which this Corner bears N. 19° W.

side of tree

tree .70 inches diameter, on the S.E.

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T 194 N R 30 W 5th Mer. 8-17