

U. S. Department of Agriculture
FOREST SERVICE

Posted

E17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W.* *5th* Mer.

Section Corner common to Sections

2, 3, 10, and 11

Corner consists of a *Br. cap. iron* in place


State condition *good*

Dimensions above ground *2"x7"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T144N R30W S11</i>	<i>SR</i>	<i>S109</i>	<i>10</i>
-------------------------------	-----------	-------------	-----------

<i>B.T.</i>	<i>B.T.</i>	<i>B.T.</i>	<i>B.T.</i>
-------------	-------------	-------------	-------------

Species *Elm Y. Birch W. Pine Elm*
 Diameter *10" 14" 40" 9"*
 Bearing *S38°15'E N39°E N49°30'W S74°W*
 Distance *29 1/2 37 80 50* lk.

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton
(Signature)


Comptroller
(Title)

10-24-34
(Date)

EAT

(Make sketch of topography near Corner)

T. 144N. R. 30W. 5th 6-17



Metal Location Poster is on a Elm

tree 10 inches diameter, on the N.W

side of tree

from which this Corner bears N38.15'W

chains distant 29 1/2

Give any further facts which will aid in finding this

Corner again.