

U. S. Department of Agriculture

FOREST SERVICE

*posted A17*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N* R. *30 W* Mer.

Corner common to Sections *2, 3, and 35*

Corner consists of a *wood pile* (not) in place  
State condition *Good*

Dimensions above ground *8'* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>S35</i>			
N	W	S	E

	<i>S3</i>	<i>S2</i>	
NW	SW	SE	NE

Mound of *✓* is located *✓*

*✓* Pits are located *✓*

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>T144 N</i>
<i>R 30 W</i>
<i>S 35 E</i>


<i>T144 N</i>
<i>R 30 W</i>
<i>S 25 E</i>


<i>N.T.</i>
-------------

--

<i>BT</i>
-----------

--

Species *Elm* *Amalgam*

Diameter *15"* *10"*

Bearing *S 25 E* *S 35 E*

Distance *35.6* *31.3*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *✓*

(Signature)


*Nov 5 '31*

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)