

U. S. Department of Agriculture

FOREST SERVICE

posted 119

Chippawa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N R. 30 W S Mer.

Corner common to Sections

36, and

Corner consists of a metal post (not) in place



State condition

Dimensions above ground 12 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Yellow Birch

Diameter 4 1/2"

Bearing S 50 W

Distance 20'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?


[Signature]
(Signature)

17 1931
(Date)

[Title]
(Title)

Corner again.
 East from old site road
 distance about 10 ft
 in line with old road
 from old road
 road was cleared
 and was 100 ft wide

Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)