

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

E-20
Posted
E-20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 30W 5th Mer.

E. Sixteenth Corner common to Sections

....., R., and 11

Corner consists of a Bear iron pipe in place
State condition good

Dimensions above ground 1" x 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine W. Pine

Diameter 9" 8"

Bearing S. 72° 45' W N. 4° 30' W

Distance 11 1/2 9 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Dorman J. Sutton
(Signature)

11-8-34
(Date)


Compassman
(Title)

E-20

Dotted lines for writing.

Corner again.

Give any further facts which will aid in finding this
..... chains distant.
..... from which this Corner bears
..... side of
..... tree inches diameter, on the
..... Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. LAMM R. 34W 5th E-20 Mer.