

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

Posted  
K21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14 N. R. 20 E. Mer.

N 1/4 Corner common to Section 13

and 14

Corner consists of a stone (not) in place



State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? no

If not, why? stone is not in place

Section 13 & 14

Signature.

Date.

Title.

Section 5035

E.C. 2000

No. 1000

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.

Sec.	Sec.
Sec.	Sec.