

U. S. Department of Agriculture  
FOREST SERVICE

A23

*already  
filled*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 N. R. 30 W. 5 th. Mer.  
N. Quarter

Corner common to Sections

36, and 1

Corner consists of a Metal pipe (not) in place

State condition Good capped

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

36		1	
----	--	---	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

N.1/4  
S.1

N.1/4  
S.1

B.T.

B.T.

Species Ash Birch

Diameter 5" 12"

Bearing S67 30 E S30 W.

Distance 40.9 Lks. 81.14 Lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Lloyd Folsom


(Signature)

Dec. 1, 1936

(Date)

(Title)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)