

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144N.* R. *30W.* *5th* Mer.

Lat Corner common to Sections

30, Lots 2, 3, 4, and 5

Corner consists of a *3" brass* iron pipe (not) in place



State condition *good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____ *None*

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Dorman J. Sutton
(Signature)


9-5-94
(Date)

Compassman
(Title)

Dotted lines for notes.

Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a *None*



(Make sketch of topography near Corner)

T. 144N. R. 50W. 5th Mer. S-1-2