

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

*Yes*  
*Pos 221*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

*1036144* R. \_\_\_\_\_ Mer.

Corner common to Sections \_\_\_\_\_

\_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a \_\_\_\_\_ (not) in place

State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_ *Dead Spruce* \_\_\_\_\_ *Redwood* \_\_\_\_\_

Diameter \_\_\_\_\_ *4.0* \_\_\_\_\_

Bearing \_\_\_\_\_ *250°* \_\_\_\_\_ *85°* \_\_\_\_\_

Distance \_\_\_\_\_ *25'* \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Signature.

Date.

Title.

Metal Location Poster is on a \_\_\_\_\_  
 tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_  
 side of \_\_\_\_\_  
 from which this Corner bears \_\_\_\_\_  
 chains distant.

Give any further facts which will aid in finding this

Corner again.

	Sec. 1		Sec. 1
	Sec. 1		Sec. 1

3-3027 (Make sketch of topography near Corner.)

T. R.

Mer. Z-21