

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

P-21

P21

Posted



Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T144N R. 31W 5<sup>th</sup> Mer.  
Quarter Corner common to Sections

\_\_\_\_\_, R3, and 24  
Corner consists of a Br. cap iron pipe in place  
State condition good


Dimensions above ground 1" x 4 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species N. Pine J. Pine stump  
Diameter 14 18  
Bearing N113°W S62°W  
Distance 27 115 1/4

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

J. A. Gjelhaug


(Signature)

2-6-35  
(Date)

Tech. Eng.  
by D. J. Suttan

Corner again.

Give any further facts which will aid in finding this  
chains disapt.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a *No Poster.*



(Make sketch of topography near Corner)



