

U. S. Department of Agriculture
FOREST SERVICE

Posted
G21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *144 N.* R. *31 W.* *5th* Mer.

Quarter Corner common to Sections
11, and *12*

Corner consists of an *Oak Post* (~~tree~~) in place



State condition *Set new Oak Post*

Dimensions above ground *4 Ft.* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Mtd. Species *N. Pine*

Diameter *1.8"*

Bearing *N. 89° E*

Use Distance *49*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *No corner there. Established*

1/4 cor. Equidistance between section corners, this being 1.79 ch. North of M.C.

J. A. Gjelhaug
(Signature)

9/9/34
(Date)

Tech. Eng.
(Title)

North of N.C. 1.79 chs.

Corner again.

Give any further facts which will aid in finding this


0.49 chains distant.

from which this Corner bears 589° W.

side of Tree.

tree .18 inches diameter, on the West

Metal Location Poster is on a N. Pine



(Make sketch of topography near Corner)

T. 194N. R. 31W. 5th. G-21 Mer.