

U. S. Department of Agriculture  
FOREST SERVICE

*Footed*

CHIPPewa NATIONAL FOREST

X23

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 31W 5th Mer.

C. Quarter Corner common to Sections

....., and 36.....

Corner consists of a *Br. Cap 1/2" dia 1"* (net) in place


State condition *good*

Dimensions above ground *6"* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ..... is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

*1/4*  
*536*

*1/4*  
*536*

*B.T.*

*B.T.*

Species *N. Pine N. Pine*

Diameter *12" 9"*

Bearing *N 57° 15' E S 91° 15' W*

Distance *42 1/4 33 3/4*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? .....

*C. J. Mendenhall*

(Signature)

*Compassman*

(Title)

*8/28/34*

(Date)

.....

.....

.....

.....

.....

.....

.....


.....

.....

.....

Corner again.

Give any further facts which will aid in finding this  
 ..... chains distant.  
 from which this Corner bears  
 side of .....  
 tree ..... inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T 194N R 31W  
 5 M X-23  
 Mer.