

U. S. Department of Agriculture

FOREST SERVICE

123

Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144N R. 31W 5th Mer. Quarter Corner common to Sections

25, and 36

Corner consists of a Br. Cap. pipe (not) in place



State condition good

Dimensions above ground 1x8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen

Diameter 9"

Bearing N14°W

Distance 10

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

J. A. Gjelhaug

(Signature)

Tech. Eng.

(Date)

2-6-35

by Ed Sutton

Corner again.


Give any further facts which will aid in finding this

chains distant.

10 from which this Corner bears S14° E

side of tree

tree 9 inches diameter, on the SE
Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. HAN R. 31W 5th V-23 Mer.