

U. S. Department of Agriculture

FOREST SERVICE

posted  
R 25

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 44 N. R. 25 E. 5th Mer.

Corner common to Sections

24, 25, 12, and 3

Corner consists of a stone (not) in place

State condition good

Dimensions above ground 7 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

50	520	30	19
NW	SW	SE	NE

Mound of   is located  

Pits are located  

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T1447 N 31° 30'		T 1447 S 21° 30'	T 1447 S 33° 30'
37	PT		

Species       R. C. C.

Diameter 1 1/2" 7" 7" 7"

Bearing N 12° W S 70° W S 30° E N 31° E

Distance 141 sh 31 30 45

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?  

   
(Signature)

   
(Date) (Title)

Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.

<p>Sec. 30</p>	<p>Sec. 25</p>
<p>Sec. 19</p>	<p>Sec. 24</p>

(Make sketch of topography near Corner)