

U. S. Department of Agriculture
FOREST SERVICE

V-1

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 & 27 5th Mer.

Section corner Corner common to Sections

25, 26, _____, and 7, 145-27

Corner consists of a metal peg (not) in place



State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS


METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No


If not, why? no evidence

Stanley M. Morrison
(Signature)

Forestry aid
(Title)

9-10-60
(Date)

T. 145 R. 25 S. 27 Mer. 5-27
 (Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a ~~corner~~ *tree*

tree 6 inches diameter, on the ~~line~~ *tree*

side of ~~the~~ *tree*

this Corner bears (Bearing) (Distance) Chains.

Section line marker between Secs. and is on

a (Tree, post, etc.) on the (Name of road, trail, etc.)

located chains E., W., N., S., from Sec. Cor.; 1/4 Cor.; Witness Cor.

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

*Also find poster S. 27
 corner*