

U. S. Department of Agriculture
FOREST SERVICE

W-6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

1/16 Corner common to Sections
~~32~~ 32, and

Corner consists of a metal tag (set) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? X

If not, why? no evidence


S. M. Morrison
(Signature)

Forester and
(Title)

Aug. 1960
(Date)

Ed E. Jones
Asst. D.F.R.

T. 145 R. 26 Mer. 5th



Metal Location Poster is on a *Timber* tree 8 inches diameter, on the *N* side of *the* this corner bears (Bearing) and (Distance) Chains. Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *For N. side of road* *the line runs N. W. E. of corner.*

