

U. S. Department of Agriculture
FOREST SERVICE

W-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.


1/4 Corner common to Sections
32, and

Corner consists of a metal tag in place
State condition

Dimensions above ground _____ inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS


METAL CORNERS



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence


Stanley M. Morrison

(Signature)

2-1-61
(Date)

V. Vestly
(Title)

(Make sketch of topography near Corner and show section line markers that "X")



Metal Location Poster is on a *Barren* tree *6* inches diameter, on the *left* side of *the* from which this Corner bears (Bearing) _____ (Distance) _____ and is on a _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) _____ located chains *L. W. N. S.*, from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Also find corner etc* *West & North of 29.*