

U. S. Department of Agriculture

FOREST SERVICE

8

Chippawa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/16 Corner common to Sections 32, , and


Corner consists of a metal tag (not) in place State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? no evidence

S. M. Morrison

(Signature)

Forestry aid


(Title)

Aug. 1960 (Date)

W. E. Rose Asst. D.F.R.

T. 145 R. 26 Mer. 5-26

(Make sketch of topography near Corner and show section line markers thru "X")



Metal Location Poster is on a *Corner* tree 12 inches diameter, on the *East* side of *the* from which this Corner bears *E. 148* (Bearing) and (Distance) Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.) located chains *R. W. R. S.* from Sec. Cor.;  $\frac{1}{2}$  Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: *Use the Poster to find East & West of corner*

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----