

U. S. Department of Agriculture

FOREST SERVICE

1714

4-9

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/12 Corner common to Sections  
32, 33, and 33


Corner consists of a square stake (not) in place  
State condition good

Dimensions above ground 3" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS


METAL CORNERS



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

*S. M. Morrison*

(Signature)

*Forestry aid*

(Title)

9-26-50  
(Date)

