

U. S. Department of Agriculture

FOREST SERVICE

2-10

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

1/14
33 Corner common to Sections
, and

Corner consists of a metal tag (was) in place


State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of boxes for recording tree bearings and distances.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

Stanley M. Morrison

(Signature)

11/20/59


(Date)

Forestry aid

(Title)

T. 145 R. 2C
 Mer. 5-2

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Red Pine* tree 12 inches diameter, on the *North* side of *Tr. 8* from which

this Corner bears *0*° (Bearing) and (Distance) Chains.

Section line marker between Secs. and is on a (Tree, post, etc.) on the (Name of road, trail, etc.)

located chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

*1320 ft. from corner
 W side of Tr. 8*

