

U. S. Department of Agriculture
FOREST SERVICE

B-10

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *26* *5th* Mer.

116

Corner common to Sections

and *4*

Corner consists of a *yellow tag* (~~rod~~) in place

State condition

Dimensions above ground *54* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *no*

If not, why? *no evidence found*

W. S. Luntz

(Signature)

8/26/59

(Date)

Asst Ranger

(Title)

Corner again.

Give any further facts which will aid in finding this

~~obvious distance.~~

from which this Corner bears


7 ft. East

side of

tree 9 inches diameter, on the East

Metal Location Poster is on a

Wood Post



(Make sketch of topography near Corner)

Mer.

57

R. 26

T. 143