

U. S. Department of Agriculture  
FOREST SERVICE

A-10

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *28 2d* Sth Mer.

*114* Corner common to Sections  
*4*, and *33*

Corner consists of a *yellow tag (not)* in place  
State condition *Good*

Dimensions above ground *54* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *No evidence found*

\_\_\_\_\_

\_\_\_\_\_

*M. K. Lantson*

(Signature)

*Asst. Ranger*

(Title)

*8/26/59*  
(Date)

Corner again.

Give any further facts which will aid in finding this

~~contains~~ distant.


*6 feet SW*

from which this Corner bears

side of

tree <sup>the</sup> 3 inches diameter, on the west

Metal Location Poster is on a *Open Bank*



(Make sketch of topography near Corner)