

U. S. Department of Agriculture  
FOREST SERVICE

A-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 572 Mer.

1/4

Corner common to Sections

4, and 33

Corner consists of a yellow tag ~~(tree)~~ in place

State condition

good

Dimensions above ground 54 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? As evidence found

M. K. Luntzer

(Signature)

Asst. Ranger

(Title)

8/26/59  
(Date)

Corner again.

Give any further facts which will aid in finding this

corner distant.

from which this corner bears


4 feet N W

side of

tree 6 inches diameter, on the

Metal Location Poster is on a

tree



(Make sketch of topography near corner)

Mer.

524

R. 26

T. 14