

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

0-13

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *76* *5th* Mer.

1/4 Corner common to Sections

....., *3*, and *4*

Corner consists of a *yellow* *log* (.....) in place

State condition

Dimensions above ground *54* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? *No evidence found*

A. K. Hamilton

(Signature)

Asst Ranger

(Title)

8/13/59
(Date)

Corner again.
Camp found on west side adjacent to road

Give any further facts which will aid in finding this


~~observing~~

from which this Corner bears 2 paces

side of

tree 7 inches diameter, on the East side

Metal Location Poster is on a Paper Birch



(Make sketch of topography near Corner)