

U. S. Department of Agriculture  
FOREST SERVICE

F-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5th Mer.

1/4 Corner common to Sections

....., and 10

Corner consists of a yellow tin (~~rod~~) in place

State condition good

Dimensions above ground 54 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

|  |  |  |  |
|--|--|--|--|
|  |  |  |  |
|  |  |  |  |

Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence found

Marvin D. Swinton  
(Signature)

Asst Ranger  
(Title)

8/19/59  
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree 8 inches diameter, on the <sup>the</sup>

*Look Point West*

Metal Location Poster is on a



(Make sketch of topography near Corner)

Mer.

574

R. 26

T. 143