

U. S. Department of Agriculture
FOREST SERVICE

D-14

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 6th Mer.

1/4 Corner common to Sections
_____, _____, and 3

Corner consists of a yellow tag (not) in place



State condition good

Dimensions above ground 54 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence found

M.K. Lountain

(Signature)

Dist Ranger

(Title)

8/13/55
(Date)

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER

SECTIONAL CORNER


SECTIONAL CORNER

Corner again.
From the corner - (E-W) (N-S)
distance 2 feet from

Give any further facts which will aid in finding this chains distant.

from which this Corner bears side of

tree 2 inches diameter, on the side of
Metal Location Poster is on a



(Make sketch of topography near Corner)