

U. S. Department of Agriculture

FOREST SERVICE

2-16

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
34, \_\_\_\_\_, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (set) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS




N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No evidence

*Stanley M. Morrison*

(Signature)

*Forestry and*


(Title)

6/17/60  
(Date)

*W. R. Tucker*

T. 145 R. 20 Mer. *50*

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Brick* tree 8 inches diameter, on the *N.* side of *the* from which

this Corner bears *NE*, *27 1/2* (Distance) and is on

Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_

a \_\_\_\_\_ on the \_\_\_\_\_

(Tree, post, etc.) \_\_\_\_\_ located

chains L, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. \_\_\_\_\_

Give any further facts needed to find Corner again:

*Blue Line Poster East & North of corner*