

U. S. Department of Agriculture  
FOREST SERVICE

4-16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
34, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (~~rod~~) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence


Stanley M. Morrison  
(Signature)

6/17/60  
(Date)

Forestry aid  
(Title)

F. W. R. Tucker

T. 145 R. 2C Mer. 52



Metal Location Poster is on a *Aspen* tree 10 inches diameter, on the *W side* side of *the* tree

from which this Corner bears *S 60° 21' W* (Bearing) and (Distance) is on Section line marker between Secs. and

a (Tree, post, etc.) on the (Name of road, trail, etc.) located chains *L. W., N., S.* from Sec. Cor.;  $\frac{1}{4}$  Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again: *These are found on S side of East of corner*