

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST



E-16 1/2

CORNERS OF THE PUBLIC SURVEY

T. *145* R. *26* *5th* Mer.
1/32 Corner common to Sections


3 and *10*
Corner consists of a *yellow log* (~~not~~) in place
State condition *good*

Dimensions above ground *54* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____
Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*
If not, why? *No evidence found*

Marvin K. Leighton
(Signature)
8/19/59
(Date)
Post Ranger
(Title)

Corner again.

Give any further facts which will aid in finding this


Like 7 corners distant.

from which this Corner bears *29*

side of *Tree*

tree *5* inches diameter, on the *west*

Metal Location Poster is on a *white Board*



(Make sketch of topography near Corner)

T. 144 R. 26 Mer. (Date) 5/21