

U. S. Department of Agriculture

FOREST SERVICE

L-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5 Mer.

1/16 Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, \_\_\_\_\_, and 18

Corner consists of a Yellow FSLP (not) in place

State condition Good

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

[Handwritten Signature] Forester

(Signature)

(Title)

3/23/61 (Date)

-----  
-----  
-----  
-----

Blue line painted N & W  
of corner

Tree is about 1/2 chs  
South of woods road.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of ~~Tree~~

tree 6 inches diameter, on the

Metal Location Poster is on a Red Pine



(Make sketch of topography near Corner)

T. 145 R. 27 S Mer.