

U. S. Department of Agriculture

FOREST SERVICE

K-4

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5 Mer.

1/16 Corner common to Sections

18

Corner consists of a FSLP (Alum) in place



State condition Good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

[Handwritten signature]

(Signature)

3/23/61

(Date)


[Handwritten title]

(Title)

Replaced old tag.

Blue lines painted West
and South of corner.
Corner again.

Give any further facts which will aid in finding this
chains distant.
from which this Corner bears
side of Tree
tree 10 inches diameter, on the South
Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)