

U. S. Department of Agriculture

FOREST SERVICE

M-6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer.

Corner common to Sections

16 and 17

Corner consists of a FSLP (A.W.) (not) in place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

Handwritten signature


(Signature)

3/23/01 (Date)

(Title)

Corner again.
Blue line painted East
and South of corner.
Replaced by red stake

Metal Location Poster is on a
tree 6 inches diameter, on the
side of *Tree*
from which this Corner bears
N - 15 W
Give any further facts which will aid in finding this
corner distant.



(Make sketch of topography near Corner)