

U. S. Department of Agriculture
FOREST SERVICE

*Map 0-6
20*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *145* N R. *27* W *5th* Mer.

1/6 Corner common to *Forties*
of the *NW 1/4*, and *Sec 20*

Corner consists of a *Squared Post* (not) in place


State condition *Some what rotten*

Dimensions above ground *2'* by *4" x 4"* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Norway Pine* _____

Diameter *12"* _____

Bearing *West* _____

Distance *30* Lks. _____

Do you believe this to be a genuine Land Office Corner? *Yes*


If not, why? _____

H. W. Korsgard
(Signature)

Dec 15, 1933 (Date) *Technical Foreman* (Title)

This corner is approximately 2. chs. South and 1/4 ch. East of the corner established by C.C.C. Surveyors.

Corner again. Give any further facts which will aid in finding this from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a chains distant.



(Make sketch of topography near Corner)

T. 145 N. R. 27 W. 5th Mer.