

U. S. Department of Agriculture

FOREST SERVICE

B-6

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 2 Mer.

Corner common to Sections 5, and

Corner consists of a metal tag (125) in place



State condition good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid of boxes for sketching trees and rocks, with two rows of four boxes each.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? no evidence

J. M. Morrison

(Signature)


Forestry Aid

(Title)

Aug. 1950

(Date)

(Make sketch of topography near Corner and show section line markers like "X")



Metal Location Poster is on a *Red oak* tree *8* inches diameter, on the *E.* side of *tree*

from which this Corner bears *NE* (Bearing) *75'* (Distance) is on

Section line marker between Secs. and is on a

(Tree, post, etc.) on the (Name of road, trail, etc.) located

chains *L, W, N, S,* from Sec. Cor.;  $\frac{1}{4}$  Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

*Blue line located S. E. of corner.*