

**U. S. DEPARTMENT OF AGRICULTURE**  
**FOREST SERVICE**

*Patel*  
*N-7*  
Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer. 5

1/4 Corner common to Sections  
20, 17, and \_\_\_\_\_

Corner consists of a squared scribed stake in place

State condition good

Dimensions above ground 2" X 2" X 24" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

		<u>1/4</u>	<u>1/4</u>
		<u>4</u>	<u>5</u>
N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u>	<u>✓</u>	<u>✓</u>	<u>✓</u>
<u>B.T.</u>			

Species Not Rec

Diameter 12"

Bearing E 40 S

Distance 2.14 ch

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Emil Jentunen

Signature.

Estimator

Title.

Date.


10/24/29

(Make sketch of topography near Corner.)

Mer.

T. 145 R. 27

5



Metal Location Poster is on a Norway Pine

tree 12 inches diameter, on the

South

side of E & W line

from which this Corner bears N 82° 30' E

2.64

chains distant

Give any further facts which will aid in finding this

Corner again.

*Edge of Spruce tapping  
written by in a  
letter of 1/1/1910*