

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST L-7

CORNERS OF THE PUBLIC SURVEY

T. 1A5 R. 27 5 Mer.

YA Corner common to Sections  
....., and 17


Corner consists of a Spaced Stake (iron) in place  
State condition Fair

Dimensions above ground 2A inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box  
and fill blanks below, giving bearings from Corner to Trees  
and Distances in Links.



Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

Walter J. Jones


(Signature)

3/28/61  
(Date)

Forester  
(Title)

T. 145 R. 27 Mer. 57

(Make sketch of topography near Corner and show section line markers thus "X")



*All in one*  
Metal Location Poster is on a *7* inches diameter, on the *East* side of *the* from which

this Corner bears (Bearing) \_\_\_\_\_ (Distance) \_\_\_\_\_ Chains. Section line marker between Secs. \_\_\_\_\_ and \_\_\_\_\_ is on a \_\_\_\_\_ on the \_\_\_\_\_ (Tree, post etc.) \_\_\_\_\_ (Name of road, trail, etc.) located \_\_\_\_\_ chains E, W, N, S, from Sec. Cor.; 1/4 Cor.; 1/8 Sec. Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again:

Blue lines painted east & south of corner