

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

F-7

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 52 Mer.

1/16 Corner common to Sections
8, _____, and _____

Corner consists of a metal (not) in place


State condition good

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

S. M. Morrison
(Signature)


Aug. 1900
(Date)

Forestry aid
(Title)

Robert E. Jones
Asst. D.F.R.

T. 145 R. 27 Mer. 5th

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Black Spruce tree 2' ^{inches} diameter, on the North side of line from which this Corner bears 0° (Bearing) and Chains (Distance) Section line marker between Secs. is on a Tree, post, etc. on the (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.; 1/2 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: Black Spruce to N. E. of Corner

