

U. S. Department of Agriculture

FOREST SERVICE

B-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 14.5 R. 27 5th Mer.

Corner common to Sections 5, and

Corner consists of a squared slab (not) in place



State condition good

Dimensions above ground 3 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of empty boxes for recording tree data, each consisting of a larger top box and a smaller bottom box.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence


J. M. Morrison

(Signature)

Forestry and

(Title)

Aug 1960 (Date)



Metal Location Poster is on a square stake

3 inches diameter, on the west side of stake

from which this Corner bears (Bearing) _____ (Distance) _____ chains. Section line marker between Secs. _____ and _____ is on a _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) _____ located _____ chains E., W., N., S., from Sec. Cor.; 1/4 Cor.; Witness Cor. _____

(Cross out nonapplicable)

Give any further facts needed to find Corner again:

Blue line poster E. of corner

of 27