

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST L-8

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5<sup>th</sup> Mer.

1/16 Corner common to Sections  
16, and 17



Corner consists of a Yellow FSLP ~~(tree)~~ in place  
State condition Good

Dimensions above ground 50 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

Robert E. Geona

(Signature)


Forester

(Title)

3/28/01  
(Date)

T. 145 R. 27 Mer. 5M

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Jack Pine tree 3 inches diameter, on the East side of the from which this Corner bears E. 0.45 (Bearing) (Distance) Chains. Section line marker between Secs. and is on a (Tree, post, etc.) (Name of road, trail, etc.) located chains L, W, N, S, from Sec. Cor.;  $\frac{1}{4}$  Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: Tag is visible from Winnie Down Road

Blue line Painted W + N from Corner. A good brushed out line runs North from Corner. An old squared stake was found near corner which was probably moved of the highway, during construction

Corner. An old squared stake was found near corner which was probably moved of the highway, during construction