

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

J-8

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5th Mer.

1/16 Corner common to Sections 8, and 17


Corner consists of a Sqd. R. Pine (not) in place State condition Good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Four sets of boxes for recording tree bearings and distances, each consisting of a larger top box and a smaller bottom box.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

Robert E. Jones

(Signature)


Forester

(Title)

3/28/61 (Date)

T. 145 R. 27 Mer. 5N

(Make sketch of topography near corner and show section line markers thus "X")



Metal Location Poster is on a Rd Pin tree 14 inches diameter, on the SE side of Tree from which

this corner bears ° (Bearing) ' (Distance) Chains. Section line marker between Secs. and is on

a _____ on the _____ (Tree, post, etc.) located chains _____ from sec. cor.; $\frac{1}{4}$ cor.; witness cor. (Cross out nonapplicable)

Give any further facts needed to find corner again:

Blue line painted N + S of of corner

Yellow FSLP on Road 3.8 chs South of corner