

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST

F-8

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 S. 5 Mer.

1/16 Corner common to Sections

8, and

Corner consists of a metal peg (lost) in place



State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? No evidence

*S. M. Morrison*

(Signature)


*Forestry and*

(Title)

*Aug. 1960*  
(Date)

*R. J. George*  
Asst. D.F.R.

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Brick*

tree *4* inches diameter, on the *East*

side of *the*

this Corner bears

Section line marker between Secs. and

is on

located

Give any further facts needed to find Corner again:

*Corner - corner on the*

*of the corner on the*

*of W. Road E.*

*# 59 - with angles*